APPLICA	BLE STAI	NDARD								
Operating Temperature Range		Range	-55 °C to 85 °	°C (1)		orage mperatur	e Range	-10 °C to	60 °C	(2)
Rating	Voltage Current		Power Contact : 200 V AC Signal Contact : 0.5 A			orage Humidity Range		Relative humidity 85	5% max	
						perating Humidity Range (Not dewe				
			SPEC	IFIC <i>A</i>	NOITA	IS				
I7	ГЕМ		TEST METHOD				REQU	IREMENTS	QT	ΑT
CONSTR	UCTION					•				
General Examination			Visually and by measuring instrument.				ing to drawing	<b>j</b> .	×	×
Marking	0.0114.0.4		ed visually.						×	×
Contact Res	C CHARAC		DC or 1000Hz)			C:1	O	- O MAY	l ×	Т
		,	, , ,				Signal Contact : 70m Ω MAX. Power Contact : 20m Ω MAX.			
Insulation Resistance		Power C	Signal Contact : 100 V DC. Power Contact : 250 V DC /1			Signal Contact : 100 M $\Omega$ MIN. Power Contact : 1000 M $\Omega$ MIN. $1$			×	-
Voltage Pro	Voltage Proof		Signal Contact : 150 V AC for 1 min.				No flashover or breakdown.			×
NEOLIA		Power Contact : 600 V AC for 1 min. 1				The flaction of production.			×	_
	ICAL CHAI					l				1
Insertion and Withdrawal Forces		Measure	Measured by applicable connector.			Insertion Force: 18 N MAX 1 2 N MIN.			×	_
Mechanical Operation		100 times insertions and extractions.			① Contact Resistance:			×	T -	
						Signal Contact : $80m \Omega$ MAX. Power Contact : $30m \Omega$ MAX.				
								ા ૩૫m છે. MAX. k and looseness of parts		
Vibration Shock		Frequen	Frequency 10 to 55 to 10Hz, approx 5min					continuity of 1 µs.	×	<del> </del>
		Single ar	Single amplitude: 0.75 mm, 10 cycles					k and looseness of parts		
		for 3 axial directions.								-
			490 m/s <sup>2</sup> , duration of pulse 11 ms at 3 times for 3 both axial directions.						×	_
FNVIRON	IMENTAL (		TERISTICS			1				
Damp Heat			at 40±2 °C, 90 ~ 95 %	, 96	h.	(1) Cor	ntact Resistar	ice:	×	_
(Steady state)						ignal Contact				
Rapid Change of Temperature		-	Temperature -55 → +85 °C			Power Contact : 30m Ω MAX.			×	_
		Time	Time 30 → 30 min. under 5 cycles. (Relocation time to chamber : within 2~3 MIN)				② Insulation Resistance: Signal Contact: 100 MΩ MIN.			
							Power Contac			
		(**************************************	(Notice and the to chamber . Wallin 2 5 Willy)			③ No damage, crack and looseness of parts.				
Cold Dry Heat		Exposed	Exposed at -55°C, 96 h  Exposed at 85°C, 96 h			① Contact Resistance: Signal Contact: 80m Ω MAX.  1 Power Contact: 30m Ω MAX.  2 No damage, crack and looseness of parts.			×	_
		<u> </u>								
		Exposed							×	-
Sulfur Dioxide		Exposed	Exposed at 25±2°C, 75±5%RH, 25 PPM for 96 h. (Test standard: IEC 68) 1			No defect such as corrosion which impairs				+-
						the function of connector.				
			_			_	ntact Resistar			
							ignal Contact			
Resistance to		1)Reflow soldering :			1 Power Contact : 30m Ω MAX.  No deformation of case of excessive			×	+-	
Soldering Heat			Peak TMP : 260°CMAX			looseness of the terminal.				
			TMP: 220°CMIN for 60sec							
Solderability		2) Soldering irons: 360°C MAX. for 5 sec.			Λ			4		
Soluerability			Soldered at solder temperature 240±3°C for immersion duration, 3 sec.					ng of solder shall cover a the surface being	×	_
		240200	r for immercion duration, o s	· · · · · · · · · · · · · · · · · · ·		immer		uno cumaco comig		
COU	NT [	DESCRIPTI	ON OF REVISIONS		DESIG	SNED		CHECKED	DA	TE
13					TS. 0	ONO		KN. SHIBUYA		9. 09
REMARKS			ure rise caused by current-carrying. ans a long-term storage state for the unused product				APPROVED	HS. OKAWA	14. 0	9. 02
	before assem	•	erm storage state for the unused pro-	ouuti			CHECKED	KN. SHIBUYA	14. 0	9. 02
,			<b>A</b>				DESIGNED	TS. 00N0		9. 02
Unless otherwise specified, refer						<u> </u>		TS. 00N0	14. 0	
Note QT:C	Qualification To	est AT:As	surance Test X:Applicable Te	est	DI	RAWIN	IG NO.	ELC-353559-0	)0-00	)
HIROSE ELECT			CATION SHEET		PART NO.		FX23-40S-0. 5SV10			
HIF		ROSE ELECTRIC CO., LTD.			CODE NO.		CL573-3302-7-00			1/1

